2.0 oz / 57 g Beeswax 0.5 oz / 14 g Carnauba 2.5 oz / 71 g Mineral Spirits 2.5 oz / 71 g Spar Urethane 7.5 oz / 213 g Boiled Linseed Oil

Melt together in double boiler. Apply to wood, warm with heat gun, let cool, wipe off excess and buff, repeat.





1.0 oz / 28 g Beeswax 0.5 oz / 14 g Carnauba 2.5 oz / 71 g d-Limonene 1.0 oz / 28 g Raw Linseed Oil 8.0 oz / 227 g Tung Oil 0.06 oz / 2 g Vitamin E Oil

Melt first 5 ingredients together in double boiler; add Vitamin E as mixture is cooling. Apply to wood, warm with heat gun, let cool, wipe off excess and buff, repeat.



